

YARBO

Save This Guide Quick Fixes for Snowstorm Errors

Mid-storm is the worst time to search through a manual. We've summarized the most common **Error Codes** and the **#1 Reason** your auger might stop spinning.



Need a visual guide on replacing the Shear Pin? Link in the comments below.

Slide 2

Auger Errors (OA Series)

● Auger



Code: OA001

Problem: Frozen or Obstructed

Fix: Check for ice/debris

➡ Tap “Clear Error” in the App Controller

Code: OA002 / OA003

Problem: Frozen or Obstructed

Fix: Let Yarbo rest briefly before resuming.

YARBO

www.yarbo.com

Slide 3 Chute & Deflector Issues

● Chute ● Deflector



Code: OC001 – OC003

Part: Chute Status: Blocked

Fix: Clear blockage

➡ Tap “**Clear Error**” in the App Controller


Code: OD001 – OD003

Part: Deflector Status: Obstructed

Fix: Clear blockage

➡ Tap “**Clear Error**” in the App Controller


Slide 4 **FAQ – Shear Pin**



Q Auger NOT spinning? A Check the Shear Pin.

Why: It connects the auger to the shaft. If it's broken or lost, the auger won't work.

Solution: Replace with a spare pin. (Check comments for video guide)



Slide 5 **Still Stuck?**

If you've cleared the blockage and the error persists, we are here to help.



Email: support@yarbo.com
Phone: +1 (631) 818-1850